# Weathertzation Assistance

## Work Order Bid (ID)

#### **WORK ORDER INFORMATION**

Work Order Name: WO/17017UC-0889/1

Work Order Type: Weatherization Audit Name: 17017UC-0889

**CLIENT INFORMATION** 

Client ID: 17017UC-0889

#### **AGENCY INFORMATION**

Agency: Upper Cumberland H R A Agency Phone: (931) 528-1127

Address: 3313 Williams Enterprise Drive Fax:
Cookeville, TN 38506 Email Address:

Agency Contact: Pridgeon, Wayne Work Phone:

Cell Phone: (931) 273-9616

Email Address:

Company Name & License Number:	
Contractor's Signature:	

#### **COMMENT**

1979 SITE BUILT HOME

### **Measures**

Measure 1 REPLACE 1 WINDOW  Comment 36X54 WINDOW				Componen	its			Inspected	
					Estimated	1		Actual	
# Materia	l / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
10 Unspec	cified	Misc Material	Each	1					
Other De	tail								
				Measur	e Sub Total:			Sub Total:	
Measu	re 2 Infil	tration Redctn			Componen	ıts			Inspected
Comme	CAULK FOUND INSTAL	5 EXTERIOR WINDOW 9 INTERIOR WINDOWS ATION ACCESS DOOR L 2 DOOR SWEEPS AN ERSTRIP 2 DOORS US	S ID THRES			IERSTRI	P		
					Estimated			Actual	
# Materia	l / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
10 Miscell Supplie		Infiltration Reduction	Each	1					
Other De	tail								
				Measur	e Sub Total:			Sub Total:	
Field No	otes:								

	Measure 3 DW	/H Pipe Insulation			Componer	nts			Inspected
	,omment				Estimated	1		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	DHW Pipe Insulation	Each	1					
		wrap water pipes							
2	Labor	DHW Pipe Insulation	Each	1					
(	Other Detail						1		
L									
				Measur	e Sub Total:		] ,	Sub Total:	
	Measure 4 Atti Comment	ic Ins. R-38			Componer			Actual	Inspected
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	Attic Insulation - Blown Cellulose - R-38	SqFt	1647					
(	Other Detail								
				Measur	e Sub Total:		] .	Sub Total:	
	Field Notes:								

Measure 5 DW	H Tank Insulation			Componer	nts			Inspected	
Comment									
				Estimated	<i>d</i>		Actual		
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total	
Hot Water     Equipment	DHW Tank Insulation	Each	1						
	R-10 minimum-use bubble wrap								
2 Labor	DHW Tank Insulation	Each	1						
Other Detail									
			Measur	e Sub Total:			Sub Total:		
	rm Windows DOWS D8 & D10: 36X54 < 54			Componer	nts D8,B2	!		Inspected	
				Estimated	<i>d</i>		Actual		
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total	
3 Other	Storm Window	Each Window	3						
	<99 U.I ea Over 100 UI								
Other Detail									
			Measur	e Sub Total:		,	Sub Total:		
Field Notes:									

Measure 7 Floor Ins. R-19				Components FLR					
Comment									
				Estimated	1	Actual			
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total	
1 Insulation	Floor Insulation - Fiberglass Batts - R-19	SqFt	1603						
Other Detail						_			
			Measur	e Sub Total:		] .	Sub Total:		
Field Notes:									
		Work Or	der Gra	nd Total:		Gran	d Total:		